W/owl.	Order	ID	651	55
Work	Uraer		カンコ	~

Thursday, January 06, 2011 3:32:25 PM



Page 1

D3257-1 Item ID: Accept Setup Start Revision ID: Stop Item Name: Fitting Start Otv: 8.00 Start Date: 1/6/2011 Cust Item ID: **Required Date: 1/14/2011** Reg'd Otv: 8.00 **Customer:** Reference: Start Run Approvals: Process Plan: Date: Tooling: Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reiect Insp. Work Center ID Description **Run Hours** Code Otv Otv Number Stamp **Draw Nbr Revision Nbr** D3257 Rev A1 100 0.00 BAND SAW Bandsaw 0.00 Memo Jeaspa Bandsaw Cut blank: 0.500" x 0.500" x 1.180" long Bar 110 0.00 HAAS CNC VERTICAL MACHINING #1 HAAS I 0.00 Memo HAAS CNC vertical machine #1 Machine as per Folio FA420 and Dwg D3257□1-Deburr□2-\*\*\*\*\*\*\*\*\*\*\*FINISH TAPPING PARTS BY HAND AS PER DWG D3257\*\*\*\*\*\*\*\*\*\*\* 120 QC2- Inspect parts off machine FAI/FAIB 0.00 M 11/03/31 

0.00

Memo

Quality Control

QC

### Work Order ID 65155

Thursday, January 06, 2011 3:32:25 PM



Page 2

Item ID:

D3257-1

Accept

Setup Start



**Revision ID:** 

**Start Date:** 

Item Name:

Required Date: 1/14/2011

Fitting

1/6/2011

OC:

Start Otv: 8.00

Req'd Otv: 8.00



Cust Item ID:

**Customer:** 

Tool ID

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling:

0.00

0.00

SPC (Y/N):

Date:

Date:

Run

Start Stop

Stop



Number Stamp

Insp.

Reject

Sequence ID/ Work Center ID

130

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Set Up/ Run Hours

B.A 11/04/04

Code Otv

Tool # Plan

Otv

Accept

Reject

140

Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

0.00

0.00

150

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

### **Picklist Print**

Thursday, January 06, 2011 3:32:29 PM

Work Order ID: 65155

Parent Item:

D3257-1

Parent Item Name: Fitting



Start Date: 1/6/2011

Required Date: 1/14/2011

Page 1

Start Qty: 8.00

Required Qty: 8.00

Com	me	nte.
CUIII	me	mts.

IPP: A□04.04.14□New issue□KJ/RF□

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M303B0.500X0.500		Purchased	No			100	f	10.6908	0.1092	0.91957	9	•	

AISI 303 Bar .500 x .500

Location MAT53

111571

10.6908 10.6908

Loc Qty

Loc Code

DART AEROSPACE LTD	Work Order:	45155
Description: Fitting	Part Number:	D3257-1
Inspection Dwg: D3257 Rev: A1		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.125	+/-0.010	127			Vern Hl	7
0.135	+0.010/-0.007	.129			+(	
1.080	+/-0.010	1.084	-	-	( )	
0.330	+/-0.010	-330			1	
0.385	+/-0.010	-385	-		11	
Ø0.191	+0.005/-0.000	\$.193			) (	
R0.193	+/-0.010	\$.193			į (	
0.887	+/-0.010	887			~l	
0.385	+/-0.010	.385	/	,	14	
0.192	+/-0.005	191	_		• •	
Ø0.230 x 100°	+/-0.010	8.235			1(	
0.135	+0.010/-0.007	.129			/\	
			·			

Measured by:	and	Audited by:	H.A	Prototype Approval:	N/A
Date:	11/03/31	Date:	11/04/04	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	04.12.10	New Issue	KJ/JLM , ,	1
В	05.06.20	0.455 dimension removed	KJ/JLM 🚓	

Dart Aerospac	e Ltd	
---------------	-------	--

W/O:			WO	RK ORDER ¢	HANGES					
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
۲.										e de la constante de la consta
							•			
Part No	:	PAR #;	Fault Categ	jory:	NC	R: Yes	No DQ	A:	Date:	
	R	esolution:	Disposition	1:	QA	: N/C C	losed:		Date: _	
NCR:			WORK ORDE	R NON-CON	FORMANCE	E (NCI	₹)			
	1		Description of NC Section A  Corrective Action De		Section B					[ ·
DATE	STEP	Description of NC Section A	Initial	Action Desc	ription	Sign	& Sec	cation ion C	Approval Chief Eng	Approval QC Inspector
DATE	STEP	Description of NC Section A	ļ		ription	Sign Date	& Sec			
DATE	STEP	Description of NC Section A	Initial	Action Desc	ription		& Sec			
DATE	STEP	Description of NC Section A	Initial	Action Desc	ription		& Sec			
DATE	STEP	Description of NC Section A	Initial	Action Desc	ription		& Sec			
DATE	STEP	Description of NC Section A	Initial	Action Desc	ription		& Sec			
DATE	STEP	Description of NC Section A	Initial	Action Desc	ription		& Sec			
DATE	STEP	Description of NC Section A	Initial	Action Desc	ription		& Sec			

NOTE: Date & initial all entries


H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE






	DESIG	RF.	DRAWN BY	DART AEROS HAWKESBURY, ONT,	
-	CHEC	(ED <sub>H</sub>	APPROVED	DRAWING NO.	REV. A
		#	et l	D3257.	SHEET 1 OF 1
-	DATE			TITLE	SCALE
	04.0	)1.27	,	FITTING	1:1
	A	uli	04.01.27	NEW ISSUE	
1	AI	-#43t	04.12.14	ADD TOLERANCE	







SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER

#### **D3257-1 FITTING**

- 1) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.015
- 2) MATERIAL: AISI 303 SS, BAR (REF DART SPEC. M303B0.500X0.500)
- 3) FINISH: NONE
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE INCHES
- 6) ENGRAVE DART P/N AS SHOWN

# **Dart Aerospace Ltd**

W/O:			WO	RK ORDER	CHANGES	3				
DATE	DATE STEP PRO		CEDURE CHAN	IGE		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		·								
			·							
				<b>2</b> - 2						
Part No		PAR #:								
	R	esolution:	Disposition	);		QA: N/C Clo	osed:		Date: _	
NCR:			VORK ORDE					, , , , , , , , , , , , , , , , , , , ,		
		Description of NC	Corrective Action		on Section	Verific	Verification		Approval	
DATE	STEP	STEP Description of NC Section A	Initial Chief Eng	Action De	scription Eng	Sign & Date		Section C	Approval Chief Eng	QC Inspector
			e.						¥ ¥	
	,									
ı							1			

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE